

Version: 181017H

Defect Corrections

- Add support for router secret key rotation without dropping BSS
- Fixed a HW initialization error
- Limit to 5 attempts on DHCP failures