

	Current	Previous
Build Version:	151226G	150821G
abSerial:	1.7	1.7
Configure Vars:	1.7	1.7

New Features

1. Added BLE security functionality for dual mode/BLE usage cases.

Defect Corrections

1. Fixed a boot up condition in the BT43, which caused the Bonding/Security calculations to fail in a rare occurrence.
2. Fixed a cause where autoreconnect did not work with DSM.
3. Fixed an autoreconnect usage case so that it can function correctly with multiple devices in the bond table.

Improvements

1. Improved DSM for the BT24H.
2. Changed the BLE custom characteristics to Write without Response types, in order to speed up throughput.
3. Adjusted the IAP2 sequence IDs for better MFI certification results.

Known Issues

1. Autosniff is not supported. Only manual sniff mode using the at+ab Sniff command.