

abSerial Firmware Release Notes

24 Oct 2016

	Current	Previous
Build Version:	160330M	160330G
abSerial:	1.7	1.7
Configure Vars:	1.7	1.7

New Features

1. Merge OTA FW for BT53i into this baseline.

Defect Corrections

1. Fix the issue that there is needless byte ('\0') in UART received data when the first connected.
2. Fix the issue that after DUT is SPPDisconnected, report "HardFault" in remote command mode.
3. Add IAP1 non-compatible reply message: "lack of backward compatibility"

Improvements

None

Known Issues

None