

abSerial Firmware Release Notes

30 Oct 2018

	Current	Previous
Build Version:	161215E	161215D
abSerial:	1.7	1.7
Configure Vars:	1.7	1.7

New Features

None

Defect Corrections

1. Fix a byte pattern receive issue for IAP2, when the data pattern is "FF5A".
2. Add support for IAP2_CUMULATIVE_ACK_MAX_CNT = 1 and IAP2_PACKET_IN_AIR_MAX_CNT = 1.
3. Improve iAP2 Reset reliability.

Improvements

None

Known Issues

None