

	<b>Current</b>	<b>Previous</b>
Build Version:	131104M	131104H
abSerial:	1.3LT	1.3LT
Configure Vars:	1.5LT	1.5LT

### **New Features**

1. Lower current consumption on one of the MCU types (STM32F101).

### **Enhancements**

1. Added a SPP Service Discovery change to improve Windows OS compatibility.
2. Add "iAPAppIDStr" configuration for iOS Request Application Launch function.

### **Defect Corrections**

1. Fixed various issues with the auto reconnect feature.
2. Fixed an error that caused a buffer to become stuck when the Apple CP was used in an incorrect manner. Normal usage is not affected.