

	Current	Previous
Build Version:	160718D	160718B
Configure Vars:	2.1	2.1

New Features

1. Add support for AP mode inactivity timeout, 120 seconds

Defect Corrections

1. Fixed some crash conditions/defects in Sndtest command
2. Fix join fail in ieee80211_scan_rx()

Enhancements

1. SPI rate increased to 42Mbps
2. Default OUT_MTU_SIZE to 1000
3. Increased the maximum number of 802.11 retries